

WORK ORDER TYPE: MODIFICATIONS

02-60456-73

ISSUE DATE 01/06/11

Page 1 Of 2

Originator	: PHILLIP HAILES	Schedule Date	:
Planner	: RONALD TAYLOR	Priority	: 3A
Drawing No	: 2SGB-M2064A	Clearance	: NO
Equip No/Cat	: 2SGB--0 2	Tag Request	:
Project ID	:	Text ID	:
Shutdown	: U Unit	Frequency	: NOT SCHEDULED
Ref No	:	Last Reading	: No Reading

Date Completed: _____ Failure Code: _____

Completed By : _____ Signature : _____

Accepted By : _____ Signature : _____

**** Delay Codes Legend ****

W=Whse C=CrSp T=Tag TL=Tool P=Plan
 ** Record Time Daily ** Delays

Step	Job Scope	MN	DY	Safety and Additional Information	Emp No	Date	Hours	Code/Hrs
1	OFA LINKAGE FABRICATION SUPPORT COST TRACKER. (PHIL HAILES)	1	1					
	PROVIDE MACHINE SHOP SUPPORT FOR OVER FIRE AIR LINKAGE FABRICATION AS REQUESTED.							
	** ADDITIONAL INSTRUCTION BY SUPERVISOR **							

**** IMPORTANT NOTICE ****

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



IP7_037483

** Work Order Parts List **								
Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd	
1	23319	STEEL, FLATBAR	S 277229	03/13/04	FT	5	0	5
2	26266	SET SCREW, 0.5-13 ALLOY	S 277317	03/13/04	EA	4	0	4
3	26272	SET SCREW, 0.5-13 ALLOY	S 277314	03/13/04	EA	0	0	0